



M & P-Xylene Concentrations In Sediment Samples (ug/Kg) Dunn Fuel Oil Spill 6-3-03



Miller Environmental
Group Figure Modified By:

Paul A. Rubin
HydroQuest
P.O. Box 387
Stone Ridge, N.Y. 12484
845-657-8111
hydroquest@yahoo.com




Figure 4